PRELIMINARY

DART AEROSPACE LTD

*

Engineering Change Notice

Date: 47/09/12		Created By: Ds A Checked: F6			
Project No					
Project No.: Project Name: 205 SKIDTUBES			Created By: S Checked: 15 Approved By: MW Approved By:		
			CPROJECT M	ANAGER) (MAN	IAGE MENT if requ
Department of Change:			5,100 EG / /1	,	- τη τοφ
Description of Change:					
REPLACE D2592	tow R	ING	WITH DZ660	TOW RING	
AS PER DSI 908	0				
	-				
Notification/Acceptance	Affected ✓		Authorization		
QA		/			
Production	V		<u> </u>		
Planning					
Marketing					
Engineering Actions	Yes	No	Responsible	To happen by:	Complete
Revise Blue File	V		DS	97/09/17	97/09/22 05
Revise Pink File	V		bS	97/09/17	97/09/22 05
Revise D-Part Master Binder					
Update Grey Project Binder	/		DS	97/09/17	97/09/22 DS
Notify TCA of Change	V		DS	97/01/30	97/12/19 KE
Notify FAA of Change	ļ	V			
Upblate DEO Binder	V		DS	97/09/17	97/09/22 15
Update Master Document List	<u> </u>				T
Non-Engineering Actions	Yes	No	Production	QA	Complete
Stock Parts:	MAMA	MIMINIO.			
Re-work current stock		V			
Scrap current stock (DZ592)		autiene			
Production Parts:		MAMA.			
Re-work current production	 				
Scrap current production (02512)	V				
Shipped Parts:		WILLIA			
Notify previous customers		CONTINUE CO			
Future Parts:		Million,			
Change future production	-	<u> </u>			
Unidate IDD		ļ			
Update IPP	1	-			
Change Paperwork for kits in stock					
Change Kits in Stock	 				
Notes:	1	<u> </u>			
Notes: REMOVE 1 ANY'S	A BO	LT AN	JD .1 D25	92 TOW RING	AND
REPLACE WITH 1					
IN ALL KITS IN					
WHO HAVE HAD A	PROBLE	EM W19	IN THE EXIS	ling you rivi	الا الا الا الوالية ا
Piladmin galicalformaless 1h dec	2	~~ ~~ m	TACMAN!	END SURE	Rev. B

P:\admin-qa\iso\forms\ecn-1b.doc

	DESIGN	DRAWN BY	DART AEROSPACE LTD VICTORIA INTERNATIONAL AIRPORT, CANADA				
Ì	CHECKED	APPROVED	DRAWING NO.	REV. A			
	KE	4	DSI 9080	SHEET 1 OF 1			
Ī	DATE		TITLE	SCALE			
İ	97.09.02		REPLACEMENT TOW RING	NTS			

DART SERVICE INSTRUCTION

TO AMEND INSTALLATION DWG D205-634 REV. A & INSTALLATION DWG D204-635 REV. A

REF. STA SH96-88 & STC SR00563NY

D2592 TOW RING CALLED UP ON THE DWG AND INSTALLED WITH AN4-51A BOLT SHOULD BE REPLACED WITH D2660 TOW RING AND INSTALLED WITH AN4-47A BOLT.

